2 October 1970

STAT   [ ] states that they are still trying to hold to the schedule put out

in June.

The computer programming work by [ ] got underway a week behind   STAT

STAT   schedule. Since then the [ ] computer broke down for 1½ weeks. [ ]   STAT

is trying to make up this time but indications are that there will be a slip

in the schedule.

The On-the- Job training of operators, programmers, and maintenance people

STAT   has been postponed until [ ] completes it's work. [ ] has the   STAT

instrument tied up for 12 hours a day.

Some modification to the new clean room will be required before the HPSC

STAT   is installed in [ ] An added 16k core memory was approved in June and

air conditioning ducts will have to be altered to cool this added cabinet. A

cable tray will have to be moved about a foot to allow maintenance of the left

illumination source. Another cable tray will have to be moved at the rear of

the instrument to allow dashpots to be installed.

STAT   [ ] will be in [ ] on 8 October and will review the

required modifications with the Support Staff and [ ] A memo has been   STAT

prepared to Chief Support Staff informing him of the required modifications

and several drawings have been exchanged by [ ]   STAT

The technical monitor will be at [ ] 5-6 October to monitor the progress   STAT

of the program.

STAT   [ ] Test Procedure is in the mail and it will be distributed to PHD

and ESD on 5 Oct. for their review and comments .

Declass Review by
NIMA/DOD